



PORT OF SEATTLE INSPECTION - DETAILED REPORT

Inspection #: 871213

Entity Information

Entity Name PORT OF SEATTLE

Primary Contact Name VIRGINIA FULLWOOD Primary Contact Phone 206-556-1678

Primary Contact Email FULLWOOD.V@PORTSEATTLE.ORG

Permit Mailing Address SUSIE ARCHULETA 2711 ALASKAN WAY, SEATTLE, WA 98121

Inspection Information

Inspection Form Annual Inspection - Escalator Inspection Status Completed (Passed - With

Deficiencies Found)

Permit # 320177 Permit Paid Date

Inspection Number 871213 Inspection Type Annual

Inspection Start Date 04/09/2025 Inspection End Date 04/09/2025

SOD Issue Date 04/09/2025 POC Due Date 07/09/2025

Expiration Date 02/01/2026

Comments

Conveyance Information

Conveyance # 22226 Conveyance Designation # 2

Conveyance/Escalator Manufacturer KONE Conveyance/Escalator Model

Site Location Address CRUISE TERMINAL, PIER 91 2001 W GARFIELD, SEATTLE, WA 98119

Inspection Team Information

·		
Name	Role	
SETH LAMB	Inspector	

Inspection Outcome - Annual

inspection Outcome - Annual				
Tag	Question	Response		
Outcome - Annual	The results of the annual inspection are as follows:	Deficiencies found		
	Remarks A002 - THIS CONVEYANCE HAS BEEN INSPECTED AND THE			
	FOLLOWING DISCREPANCIES WERE NOTED AND SHALL BE CORRECTED WITHIN 90 DAYS, WHEN CORRECTIONS ARE			
	COMPLETED PLEASE INDICATE IN THE BOX PROVIDED NEXT TO			
	EACH DISCREPANCY THAT IT HAS BEEN COMPLETED. UPON			
	COMPLETION OF ALL CORRECTIONS, OWNER, PLEASE DATE AND			
	SIGN BELOW AND RETURN A COPY OF THIS REPORT TO OUR OFFICE			
	BY THE DUE DATE.			

Annual - Es	scalator	
Tag	Question	Response
1	Operating Certificate Posted and Current - RCW 70.87.090 Inspector Comments: Operating Certificate posted is expired.	Deficiencies found - 90 day correction required
34	Must keep handrails free from cuts, cracks, pinch points and other hazards &.11.4.1(c)	Deficiencies found - 90 day correction required
	Inspector Comments: Split Handrail Left side.	
35	Must keep covers secure, no tripping hazards, maintain open area for a&& • · · · · · · · · · · · · · · · · · ·	No apparent deficiencies
36	Must keep safety decals or signs in good shape for passengers to read Å 进F註 注ÇD	No apparent deficiencies
37	Must keep comb teeth and escalator step edges operable, demarcation means - 8.11.4.1(g)	Deficiencies found - 90 day correction required
	Q•]^&{ ÁÔ[{ { ^}o MkÜ^] æ&^Áaæ{ æ*^åÁa°]•ÈMÔ@&\Ás[{ àÁ æ*\ÐÁææÁ andings formissing teeth. Replace as needed.	
38	Must maintain gap between moving step and stationary skirt panel 3/16-1/4. E\$.11.4.1(q)	Deficiencies found - 90 day correction required
	Inspector Comments: Snag point bottom side brush cover, remove snag point.	
39	Must keep excessive play or rocking movement in steps to a minimum - A 住民主任	No apparent deficiencies
40	Check MCP Cat 1 info, tasks w/dates, tests, repairs, callbacks, start-up *	No apparent deficiencies
41	Check emergency stop switch and cover alarm operable if provided - &.11.4.1(j)	Deficiencies found - 90 day correction required
	Inspector Comments: Stop switch cover must be operational,80dBA minimum.	
Additional	Inspection Items	
Tag	Question	Response
ADDL 1	V@Á[[¸ā]*Ásc^{Á^•* c^åÁsjÁs^-a8cā}}8an•Á[*}åkÁ	N/A
ADDL 2	V@Á[[¸ā]*Ásc^{Á^•` c^åÁsjÁs^-a3&a^}&a^•Á[ˇ}åKÁ	N/A
ADDL 3	V@Á[[¸ā]*Ásc^{Á^•` c^åÁsjÁs^-a&an}&an-Á[`}åhÁ	N/A
ADDL 4	V@Á[[, ā] *Ánc^{Á^•` c^åÁnjÁn^-a8an} &an•Á[*}åKÁ	N/A
ADDL 5	V@Á[[¸ā]*Ánc^{Á^•` c^åÁnjÁn^-a8ban}8an•Á[ˇ}åkÁ	N/A
ADDL 6	V@Á[[, a] *Ánc^{Á^•` c^aÁnjÁn^-a8an} 8an•Á[`}åkÁ	N/A
ADDL 7	V@Á; [¸ā)*Ánc^{Á^•` c^åÁnjÁn^-a8an}8an•Á;`}åkÁ	N/A
ADDL 8	V@Á; [¸ā;*Ánc^{Á^•` c^åÁnjÁn^-a8an}8an•Á;`}åkÁ	N/A
ADDL 9	V@Á([, ā) *Áec^{Á^•` c^åÁnjÁa^-ææa} &æ•Á(`}åkÁ	N/A
ADDL 10	V@Á; [¸ā;*Áec^{Á^•* c^åÁg,Áa^-a&a*}&a*•Á;*}ånÁ	N/A

Printed On: 04/11/2025	Inspection #: 871213	Page 3 of 3
call us at (360) 902-6130. Please i	nclude your inspection Number in your c	communication
If you have any questions, please	email the Elevator Program at <u>elevatorse</u> nclude your Inspection Number in your o	ect@lni.wa.gov or you can