



SEATTLE-TACOMA INTERNATIONAL AIRPORT

SEA

AVIATION OPERATIONS

SAFETY BULLETIN

Aug 2, 2023

Safety Reminder for ALL Drivers on the Ramp

Not following drive lanes and vehicle service roads is one of our top issued citations year to date. Cutting through gates increases the risk of collisions especially when a nearby roadway or driving area is available for use. This is also a violation of the Seatac Rules and Regulations and drivers who do not use VSRs when available can be issued citations for these violations.

CUTTING CORNERS IS PROHIBITED



STAY ON THE VEHICLE SERVICE ROAD (VSR)

CUTTING CORNERS IS PROHIBITED



**STAY ON THE VEHICLE
SERVICE ROAD (VSR)**

CUTTING CORNERS IS PROHIBITED





STAY ON THE VEHICLE SERVICE ROAD (VSR)

FOR IMMEDIATE NOTIFICATION, DISTRIBUTION & COMMUNICATION
Please Forward to ALL Airport Staff

[CONTACT US](#)

For follow up questions please contact SMS Team at SMSspecialist@portseattle.org