



SEATTLE-TACOMA INTERNATIONAL AIRPORT

SEA


AVIATION OPERATIONS

OPERATIONAL CHANGE

March 26, 2021

EFFECTIVE IMMEDIATELY

Please note the following revision to the Vehicle Service Road (VSR) near Gates A3-A5 to accommodate changes to the gates. The old VSR has been eliminated. All drivers should be reminded that Port of Seattle Rules & Regulations require drivers to utilize VSRs where present.





FOR IMMEDIATE NOTIFICATION, DISTRIBUTION & COMMUNICATION
Please Forward to ALL Airport Staff

Contact Us