


Figure 1: Program Area



Service Layer Credits: Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community

Mosquito control measures to be undertaken at the following SEA stormwater ponds (south - north):

- | | | | |
|---|-----------------|------------------------|--------------------|
| 1. SDD06A (Logistics Construction Pond) | 6. IWS Lagoon 1 | 11. TRACON Pond (East) | 16. SDN1 Pond |
| 2. SDS4 Pond | 7. IWS Lagoon 2 | 12. TRACON Pond (West) | 17. Pond SDN 2/3/4 |
| 3. BMP-D6a-3 | 8. Pond F | 13. 160th Loop Pond | 18. NEPL Pond |
| 4. IWS Lagoon 3 | 9. ASR Pond | 14. Pond G | |
| 5. SDE4 Pond | 10. Pond D | 15. Pond C | |

0 0.25 0.5 Mi.

